Work Order ID 58258

Monday, May 03, 2010 8:59:47 AM



Page 1

Item ID:

D3914-041

Accept

Setup Start

Stop



Revision ID:

Item Name:

Long Basket Lid Assembly (350)

Start Date:

5/3/2010

QC:

Start Qty: 1.00

Required Date: 5/7/2010

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: ______

Date: <u>10-5-3</u> Tooling: Date:

Date:

Date:

Start Run

Stop

Sequence ID/ Work Center ID Operation Description

Large Fab

Revision Nbr

Set Up/ **Run Hours**

0.00

0.00

SPC (Y/N):

Draw Number

Draw Plan Rev. Code Qty

Reject Accept Qty

Reject Number

Insp. Stamp

Draw Nbr-D3914

Α

100

Large Fab

Large Fab

Memo

1- assemble ribs, weld as per dwg D3914

2- weld hinge (3) and Mounting brackets as per dwg D3914

inspect before welding mesh

Weld per dwg A/R S.S. rod Batch: 111679

3- tack weld mesh on basket as per dwg D3914

Cpl 10.05.000

Memo

QC9- Inspect visual per QSI004- Fusion Welds

0.00

A 10.05.10

Quality Control

0.00

Dart Aerospace Ltd

W/O:			WORK ORDER CHANGES								
DATE	STEP	PRO	PROCEDURE CHANGE						Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		,									
		.									
·		ı					ļ				
Part No	•	PAR #:	Fault Cate	gory:	NC	R: Yes	No DQA	; ;	Date:		
			Disposition: QA: N/C Closed: _								
NCR:		· V	VORK ORDI	ER NON-CONFOR	RMANCE	(NCR)				
DATE	STEP	Description of NC		Corrective Action	Section B		Verifica	ation	Approval	Approval	
DAIL	JILI	Section A	Initial Chief Eng	Action Descripti Chief Eng	on 	Sign & Date	Sectio		Chief Eng	QC Inspector	
								:			
								1			
							·				
		1				,		1			
	-	l									
		1									
		i									
		ı									

Work Order Monday, May 03,	<u> </u>	9		Page 2					
Revision ID: Item Name: L	ong Basket Lid Assembly (350) (3/2010 Start Qty: 1.00		Accept	Set	up Star Stop				
Required Date: 5/ Reference:	77/2010 Req'd Qty: 1.00			Cust Item ID: Customer:					
	Process Plan:		_ 8	Date:		Ru	n Star Stop		
Sequence ID/ Work Center ID 120 QC Quality Control 130 Powdercoat Powder Coating	Memo T C	· · · · · · · · · · · · · · · · · · ·	Set Up/ Run Hours 0.00 0.00 0.00 0.00	Number Rev.	Plan Ac Code Qt	-	Reject Qty	Reject Number	Insp. Stamp

HandFinish

Hand Finishing

Wing Walk as per dwg QSI005 4.4 Batch # Hours

0.00

1- Mask data plate and apply wing walk on outside surface of mesh as per dwg

2- Install placard and label as per dwg

O pt 10-5-10.

Dar	t A	ero	sp	ac	е	Ltd
-----	-----	-----	----	----	---	-----

	-										
W/O:				Ì							
DATE	STEP		PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		l									
		Į.							<u> </u>	 	
								11			
										ļ	
		i	ı								
Part No	•		PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:					
					1;		İ				
NCR:			1	WORK ORDE	R NON-CONFORMA	NCE (NC	CR)				
DATE	STEP	Desc	ription of NC		Corrective Action Secti		Verif	ication	Approval	Approval	
DATE	SIEF		Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da	1& ∣ _{Sec}	tion C	Chief Eng	QC Inspector	
			1	,							
•			1								
						·		· •			
		,						1			
			I								
			I					l İ			
			İ								
l	1 1			1 !		ŀ			J	1.	

Work Order ID 58258

Monday, May 03, 2010 8:59:47 AM



Page 3

Item ID:

D3914-041

Accept

Setup Start

Stop



Revision ID:

Item Name:

Long Basket Lid Assembly (350)

Start Date:

5/3/2010

Start Qty: 1.00

Required Date: 5/7/2010

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _____ Date: ____

Date:

Tooling:

SPC (Y/N):

Date: _____

Date:



Sequence ID/ **Work Center ID**

OC

Quality Control

Operation Description

QC3- Inspect Part Finish

Memo

Set Up/ **Run Hours**

0.00

0.00

Run

Start Stop

160

Packaging

Packaging

Draw Number

Draw Rev.

Plan Code

Accept Qty

Reject Reject Qty Number

Insp. Stamp

Identify as per dwg & Stock Location: 6A 0.00

(6 533/2)

0.00

170

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo


0.00

W/O:			WORK ORDER CHANGES											
DATE	STEP		PR	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
			,			•								
•														
			<u> </u>											
Part No	Part No:			Fault Cat		NCR	l: Yes N	lo DQA:	A: Date:					
	Re	esolution:	1	Dispositi	on:	QA:	N/C Clo	sed:	ļ	Date: _				
NCR:			· · · · · · · · · · · · · · · · · · ·	WORK ORI	DER NON-CONFOR	RMANCE	(NCR))						
DATE	STEP Desc		ription of NC	Initial	Corrective Action					Approval	Approval			
DAIL	SILF		Section A		Action Descripti Chief Eng	on	Verifica Section		Chief Eng	QC Inspector				
											3			
			•					ļ						
			<u> </u>											
									İ					
			I											
			:						!					
		1		[1				

Picklist Print Monday, May 03, 2010 8:59:46 AM Work Order ID: 58258 Parent Item: D3914-041 Long Basket Lid Assembly (350) Parent Item Name: **Start Date:** 5/3/2010 Required Date: 5/7/2010 IPP Rev:A new issue DD 10.03.19 verified by:EC Comments: Start Qty: 1.00 Required Qty: 1.00 Component Item ID/ Replacement Mfg/ Bin Primary Last Route Unit of Qty on Qty per Kit Qty Date Item Name Item ID Purch Item Location Location Seq ID Measure Hand Issued Issued D2581 Manufactured No 100 Each 27.0000 2 Mounting Bracket Location Loc Qty Loc Code WA 27 46086 2 51745 2 57185 23 D2728-3 Manufactured No 140 Each 0.0000 Dart Logo label D3914-1 Manufactured No 100 Each 0.0000 Rib D3914-7 Manufactured No 100 Each 2.0000 Location Loc Qty Loc Code WA 2 57573 D4016-3 Manufactured No 100 Each 13.0000 Hinge Half, Lid

Page 1

Status



Dart Aer	ospac	ce Ltd
----------	-------	--------

W/O:				-	,					
DATE	STEP	PRO	CEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									,	
								i		
										•
		: `								, L
Part No	:	PAR #:	_ Fault Cate	gory:	_ NCR	:Yes N	io DQA		_ Date: _	
		esolution:								
NCR:		W	ORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC		tion B	0: 0	Verific	ation	Approval	Approval	
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	n C	Chief Eng	QC Inspector
									i	
										
		·						(
								j		
		,								
				•						
		!								
								i		

Monday, May 03, 2010 8:59:46 AM

Work Order ID: 58258

D3914-041

Parent Item Name: Long Basket Lid Assembly (350)

Parent Item:

Start Date: 5/3/2010

Required Date: 5/7/2010

	Comments: IP	P Rev:A new is:	sue DD 10.03.19	verifie	ed by:EC				9	Start Qty: 1.00		Required Qty:	1.00
	Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Qty Issued	Date Issued	Status
•	D4018-5	12	Manufactured	No		the second	100	Each	0.0000	3 <u>5</u>	8244-	₹9 (g	10.05.0
ſ	D4020-5 Mesh (350 Basket Long, Lid)		Manufactured	No			100	Each	1.0000	1	Cpl	10.05.0	05
		, i	,		Locatio	<u>n</u>	Loc	<u>Qty</u>	Loc Code		•		
^	D4021-3		Manufactured	No	WA	58041	100	I I Each	2.0000		<u>(i)</u>	Λ	- - - -
	Data Plate		wandiactured	7.0		•	100	Each	2.0000			(f)	005.03
	*.				<u>Locatio</u>	<u>n</u>	Loc (<u>Oty</u>	Loc Code				
					WA			2	_				4
	D4035-041		Manufactured	No		56050 57109	100	1 1 · Each	1.0000	, €	D		1
	Lid Rib Assembly, Fwd (350	Basket)	: 									plo	· <i>05</i> ·03
					<u>Location</u> WA	_	<u>Loc (</u>	Qty 1	Loc Code	- <u>-</u> -	~		:
	D4035-043		Manufactured	No		57575	100	l Each	1.0000		Ď <u> </u>	Glio	·0503
		•			Location	<u>1</u>	Loc (<u>Oty</u>	Loc Code			V	1
					WA ·	56983		1		7	D		1

Monday, May 03, 2010 8:59:47 AM

Shop Packet Print

Page 2

Dart Ae	rospace Lt	td							
W/O:			WC	RK ORDER CHANGES	S				
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
		1							
	-	İ							
Part No		PAR #:	Fault Cate	Jory:					
_	Resc	olution:	Disposition	:	QA: N/C C	osed:		Date: _	
NCR:				R NON-CONFORMAN					
DATE	OTED	Description of NC		Corrective Action Section	Section B			Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Verific Section		Chief Eng	QC Inspect
		F							
		1							
							i i		

							1		
}		[
					·				

Picklist Print

Monday, May 03, 2010 8:59:47 AM

Work Order ID: 58258

Parent Item:

D3914-041

Parent Item Name: Long Basket Lid Assembly (350)

Comments:

IPP Rev:A new issue DD 10.03.19 verified by:EC



Start Date: 5/3/2010

Required Date: 5/7/2010

Page 3

Status

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Qty Issued	Date Issued	<u>\$</u>
D4086-210		Manufactured	No			140	Fach	8 0000	1			



Placard, Max Load

 Loc Qty
 Loc Code

 ST112
 8

 56978
 8


Monday, May 03, 2010 8:59:47 AM

Shop Packet Print

Page 3


Dart Aerospace Ltd

	•										
W/O:				;		***					
DATE	STEP		PROCEDURE CHANGE By						Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			:								
<u> </u>]										
Part No	•		PAR #:	Fault Cate	egory:	NCR: Yes No DQA: Date					
	R	esolution: _		Disposition	on:	QA:	N/C Cld	osed:	<u> </u>	Date:	
NCR:			.:	WORK ORD	ER NON-CONFORM	ANCE	(NCR)			
DATE	STEP	Des	cription of NC			tion B	0: 0	Verifica	ation	Approval	Approval
			Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Sectio	n C	Chief Eng	QC Inspector
									ı		·
			ı						; 		
		:									
									1		
1		i		1				1	I	I	1




Dart Aerospace Ltd

W/O:,					WORK OF	RDER CH	ANGES	4"				
DATE	STEP	PROCEDURE CHANGE					Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		!										
		·										1
		:		·								
					,							
Part No	•	[PAR #:	Fault	Category:		NC	R: Yes	No DQA		Date:	
Resolution		esolution:		Disposition: QA				A: N/C Closed: Date:				
NCR:				WORK (ORDER NO	N-CONFO	RMANCE	(NCR)		,	
DATE	STEP	Descr	iption of NC Section A	Initia	I Act	ve Action tion Descrip	Section B	Sign &	Verifica Section		Approval Chief Eng	Approval QC Inspector
				Chief E	ng	Chief Eng		Date				
			·									
·												
		; ; .				7.			•	Į		·
						,		,				
												. '
										 	٠	
			•									




Dart Aerospace	Ltd	d
-----------------------	-----	---

	-		1								
W/O:			WORK ORDER CHANGES								
DATE	STEP		PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			ſ						ļ		
			ı								
		,	PAN, AM	·			-		1		
		,									
		1									
Part No:		1	PAR #:	Fault Cate	egory:	NCR	: Yes I	No DQ	A:	_ Date: _	
Resol		esolution: _		Disposition:			QA: N/C Closed: Date:				
NCR:		!		WORK ORE	ER NON-CONFORM	IANCE	(NCR)			
DATE	STEP	Description of NC		Corrective Action Section B Initial Action Description				Verific	ation	Approval	Approval
DAIL	JILF		Section A		Action Description Chief Eng	otion Sign & Date		Secti		Chief Eng	QC Inspector
		1							†		
		1	•						! 		
		r									
								1			
				·							
		į.									
		1									<u> </u>
		i							'		
		Ē									
	l İ			1				1	,		ŀ



Dart	Aeros	pace	Ltd
------	-------	------	-----

W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
		ļ										
							:					
Part No	:	PAR #:	Fault Cate	egory:	_ NCR: Yes	No DQA	;	Date: _				
			on: Disposition:				Date:					
NCR:			WORK ORE	DER NON-CONFORMA	NCE (NCR	1)						
DATE	STEP	Description of NC	Initial	on B	Sign & Verific			Approval				
		Section A	Chief Eng	Action Description Chief Eng	Date	Section	n C 	Chief Eng	QC Inspector			
							!					
		:										
		İ										



Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:		WORK ORDER CHANGES							
DATE	STEP	1	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		,							
		,							
		r t							
Part No		PAR	#: Fault Cate	egory:	_ NCR: Yes	No DQA	\:	Date: _	
							Date:		
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCR)			
DATE	STEP	Description of	NC	Corrective Action Sect		Verific	cation Approval		Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector	
•		r I			·				
								-	
		1							
						-	'		
	6								
		'							
		2							
		ı							